

ATTENTION

READ ME FIRST

With the upgrade to OpenBoot™ PROM 4.15 and later, diagnostics are enabled by default. This will ensure complete diagnostic test coverage on the initial boot and after error reset events. This change will result in increased boot time.

To change the system defaults and diagnostic settings after the initial boot, please refer to the attached document, *OpenBoot PROM Enhancements for Diagnostic Operation* (part number 817-6957). You can also view or print this document at:

`http://www.sun.com/documentation`

